


Optimum Instruments Flow Meter Cable



Open the lid which is held down with 4x machine screws and loosen the cable gland. Undo the currently installed cable from the screw terminals and slide it out.

Slide in the new upgraded cable and insert the wires into the terminals as shown. Tighten gland and replace lid.

Seametrics Mag Meter	Cable Wires	Connector Pin
Power + (12V)	Red	1
Power – (GND)	Black	3
Forward + (Signal +)	Orange	2
Forward – (Signal -)	Brown	4